

DEPARTMENT OF THE AIR FORCE
HEADQUARTERS OGDEN AIR MATERIEL AREA (AFLC)
HILL AIR FORCE BASE, UTAH 84401

21 OCT 1971




REPLY TO
ATTN OF:

MEMDP/

SUBJECT:

Model 1540-1 Light Table Power Cord and Reel Assembly, Contract

TO:



1. OAMA/MEDP has reviewed your letter of 6 Oct 1971. We have determined that to exchange the existing 20 foot power cord and reel assembly for 20 feet of heavier duty wire, to be hung on the side of the elevating stand, is not acceptable. The specification states that a retractable, lockable power cord be supplied and it is our desire that this be done.

2. We believe that a larger, more powerful reel assembly, which will handle the heavier wire, is required. It is not the intent of the specification to allow the full length of the power cord to be extended in order to facilitate cooling of the wire. It is intended that the user have the capability to retrieve as much cord as required to reach the power supply with the balance neatly contained on the reel assembly.

3. The 16 gauge HPN heater cord originally supplied is just too light to handle the power requirements of the 1540. A larger wire, and if necessary reel assembly/canister, is definitely required.

4. This situation has been under consideration now for nearly eight months, and we are very anxious to bring the problem to close. Prompt, favorable action will be greatly appreciated.

Cy to: USA Communications Service Gp
NAS Moffett Field, Ca 94035

USAF review(s) completed.

Declass review by NGA/DoD